CORESAN® s.r.I. CONSERVATION AND RESTORATION OF FINE ART AND CULTURAL HERITAGE



CORES4N srl C.F. e P.IVA 03050790124 Via Raffaello Sanzio, 6 I-21040 Venegono Sup. (VA) Tel/ FAX: (+39) 0331 85 01 58 Mobile: (+39) 340 370 2 370













CORES4N srl works in the wider field of the protection and the valorization of the Cultural Heritage. Its activity is directed mainly towards architectural and monumental properties.

The headquarter is located inside the Milan, Como, Varese triangle, which allows to be active in Lombardy, but remaining able to develop projects in the rest of the national territory and abroad.

The enterprise has all law requirements to intervene on architectural and monumental properties which are under the protection of the Italian ministry of culture.

The enterprise's management strategy has allowed a swift acquisition of the UNI EN ISO 9001:2015 (IAF:28) certification.

The society holds collaborations with different Italian universities, such as University of Florence, the University of Milan, the University of Bologna and the Polytechnic of Milan.











What do we do?

- Conservation and Restoration designs
 Endoscopic and thermographic
 investigations
- Conservation and restoration intervention:
 - Wall paintings
 - Stone materials
 - Plaster
 - -Stuccoes

Technologies applied to cultural heritage:
Biotechnologies
Nanotechnologies












What are we capable of?

Design and execution of restoration projects

Preventive Conservation

Movement and Packaging of art

Consulting activity









2007- Ultima Cena di Bernardino Luini- Lugano - CH











2006- San Pietro in Ciel d'Oro-Pavia- Italy

On the vault of the nave a combined technique, called BIONANO, has been used to solve the issues regarding the presence of sulphates on the painted surface.

















2002- Fontana di Piazza Camerlata Como- Italy




Conservative consolidation and restoration of the fountain located in Piazza Camerlata (1936) in Como.



2009-2011 Castello Sforzesco di Vigevano – Italy

Restoration works of the plasters, mural paintings and decorative apparatus of the main tower of the Sforza Castle of Vigevano.





2007-2008- Ex Chiesa di San Giulio- Cassano Magnago- Italy


Conservation project of the mural paintings. Use of laser Scanner 3D reliefs to study the surviving structure of the Sacristy.

























2008-2009- Annunciation Cave Saint Joseph Church Conone Cave – Holy Annunciation Nazareth- Israel


Cleaning intervention, desalination and securing of the mosaic surfaces. Securing of the painted surfaces.

Securing of the stony surfaces of the Holy Cave with nanoparticelle of Calcium Hydroxide (IV/V° AD).











2010- Villa Mia- Torno- Como- Italy

Three-dimensional relief with laser - scanner aimed to understand the shape and the position of the missing anatomic parts using biometric studies. Virtual modelling of the incomplete anatomic parts.


Preliminary prototyping with polymetric material and final rebuilding of the missing part.
















2014- Conca dell'incoronata-Milan- Italy The restor

The restoration project has been done in a laboratory. The preliminary steps were the cleaning and the disinfection of the wooden parts and the substitution of the rotting parts.










The wooden surfaces have been then subjected to cleaning or to treatments preventing further biological attacks.











2008-2010- Castello del Baradello- Como- Italia

Restoration of the stony surfaces of the Tower and the defence walls.













2011-2012- Cattedrale di Sant' Eusebio-Vercelli- Italy

Chapel of Saint Ambrogio - Removing paint and Restoration of the wall paintings -XVI/XVII cent. - Lot 2F, **Reassembling and** restoration of the high altar, Restoration and conservative reconditioning of the facade, the sides, the interior of the attic and the sculptural elements - Lot 2°





2018-2019- Duomo di Milano- Italy



The state of conservation of the spire is conditioned by the exhibition to the atmospheric agents. This happens particularly in correspondence of the statues, of the pinnacles and of the decorations.




The principal restoration operations, which are being done, are preconsolidation, cleaning, biohazard treatments and consolidation.



2011-2014- Casa Rustici- Milano- Italia

The state of conservation was marked by not efficient maintenance practices and by a wrong runoff system. Due to cracks there had been some collapses of the concrete at the balconies boards. This was caused

Through a common operation of consolidation, cleaning and protection of the marble it was possible to return a masterpiece of rationalist architecture to the city.





2017- Torre Mozza-Rocca di Arona – Lago Maggiore– Italia

The state of conservation was marked by cracks inside the walls that needed consolidation.

Reconstruction of the building crests with the predisposition of runflow system. Covering of the roof.











2016- Palazzo Piatti Reghenzani – Casa del Cuco'- Teglio- Italia

Enhancement of the garden, restoration of the annex building and frescoes of the rooms on the first floor.












2016- Statua di Giulio Ricordi-Piazza della Scala- Milano- Italy

Conservation and Restoration of the Statute of Giulio Ricordi.





2018- Municipio di Castelfiorentino- Italy

Restoration and conservation of the external pediments of the town hall









2001- Chiesa di Santa Maria della Misericordia - Ascona-Svizzera

· Quality · G · Tohaney · baptisaur xmin -

Conservation and Restoration of the frescoes of the church choir.



Interventi di conservazione e di restauro delle pitture murali del coro della chiesa



2013- Basilica di Sant'Ambrogio- Torre dei Canonici – Milan- Italy

Conservative consolidation and restoration of the bell-tower of the Canonici.









2007-2008- Monumento ai Caduti – Gallarate



Removal of the bronze sculptures and disassembly of the Monument in pink granite from Baveno.

Restoration of the bronzes and of the stony elements.
Reassembly of the monument in a New location.



